

CASE STUDY

A DAMAGED SPA RECEIVES REJUVENATION

BACKGROUND:

A tri-marble spa had significant damage in the lower corner, causing it to leak and become unusable. The owner was looking for a fast and cost-effective alternative to replacing the spa.

SOLUTION:

A Hawk-trained surface repair professional patched the holes and cracks in the challenging corner radius. Then, the patched area was coated using a combination of Redux $^{\text{TM}}$ 650 bases and tints, blended on-site, to achieve the multiple color shades required in this complex trimarble design.

RESULTS:

The satisfied owner put the spa back into use the next day, with confidence that the repair would withstand the harsh, hot, chlorinated water required for extended daily use.

APPLICATOR TESTIMONIAL:

"The actual painting process was nerve racking, but it worked out pretty well, especially for the first time I've ever tried to paint something like this tub. I think the magic is in applying multiple layers. I started a little too light and slowly progressed through the color matrix until it matched up. The customer was very happy with the repair, so I'm happy." - Lewis M., Cumming, GA



ABOUT HAWK:

Hawk is the recognized industry-leading manufacturer of professional resurfacing and surface repair systems used in residential, commercial and industrial applications worldwide.

We develop high performance premium products with attractive colors and designs and enhanced functionality. These systems are a cost-effective alternative to renovation.

